

CLASSIFICATION REPORT
INTERTEK TESTING SERVICES NA INC.
OAKDALE, MN 55128

Job No. 3051840
3068481
3068733
3071985
3072755
3073785
3082238

Issued: 04/29/04
Revised: 08/17/05

REPORT NO. 3051840.001
INSPECTION, TESTS AND EVALUATION
of

*HIGH ENERGY CLINAC LINEAR ACCELERATOR WITH ON BOARD
IMAGER OPTION

RENDERED TO
Varian Medical Systems, Inc.
*Palo Alto, CA

GENERAL: This report gives the results of the inspection, tests, and evaluation of the High Energy Clinac with On Board Imager option (2100C, 2100CD, 2300CD, 2100SC, 21EX, 23EX, Trilogy, iX)for compliance with the requirements of the Standards for Medical Electrical Equipment, Part 1: General Requirements for Safety, UL 60601-1, first edition: 2003, and CAN/CSA-C22.2 No.601.1-M90. Couch was not evaluated (see ITS Report 03011795). This investigation was authorized by Varian Medical Systems, Inc., P/O 679801 dated 12/8/03. A Product Line sample in good condition was provided by the client on 02/09/04 and evaluated at Varian Medical Systems, CA manufacturing facility.

**MEDICAL ELECTRICAL EQUIPMENT, PART 1: GENERAL
REQUIREMENTS FOR SAFETY UL 60601-1, first edition: 2003 and CAN/CSA-
C22.2 NO. 601.1-M90**

Applicant: Varian Medical Systems, Inc.
911 Hansen Way, M/S C-080
Palo Alto, CA, 94304

Contact: Mr. Fred Prudencio,
Phone: (650)424-6826
Fax: (650) 842-5078

Manufacturer: Varian Medical Systems, Inc.
911 Hansen Way, M/S C-080
Palo Alto, CA, 94304

Contact: Mr. Fred Prudencio,
Phone: (650)424-6826
Fax: (650) 842-5078

An independent organization testing for safety, performance, and certification.

This report is for the exclusive use of ITS's Client and is provided pursuant to the agreement between ITS and its Client. ITS's responsibility and liability are limited to the terms and conditions of the agreement. ITS assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to copy or distribute this report and then only in its entirety. Any use of the ITS name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by ITS. The observations and test results in this report are relevant only to the sample tested. This report by itself does not imply that the material, product, or service is or has ever been under an ITS certification program.